ECS Configuration Change Request			, P	age 1 of	1	Pages
	Date 4/28/98	Rev	Request	Туре (	CR	
Priority Routine X Urgent	Emergency	Affected Release	se V2.0	Change	Class	II
Title (description) Reallocate SPARC 20-50 SX from V2.0 hardware pool to GDAAC M &O Science Coordinator.						
Documents Affected	Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or Tech Reference					
NONE		N/A				
RTM Change Start New Baseline						
Problem  The GDAAC M&O Science Coordinator has one of the original M&O systems deployed in the field. The system is a DEC Alpha 3000/300, EIN 00000021. Due to the age of the system, the hardware could not support the required Operating System upgrade.						
Proposed Solution Reallocate from the Version 2.0 hardware pool a SUN SPARCStation 20-50 SX, EIN 00000406 for the GDAAC M&O Science Coordinator to replace obsolete current hardware.  10 10 10 10 10 10 10 10 10 10 10 10 10 1						
Impact Analysis:			FOS [	_	M&O	[X]
Organizations Affected: BOO  Procurement  Science Off  Security	Contracts	ECS Chief Eng Rel. A Sys. Eng X	Rel. C Sys Verf Acpt	•	CDO Arch.	_
Cost: None X	Small [	Medium  (\$100,000 to \$500,000)	Large (Over \$500,00	] ∞)		
Schedule: None X  Additional LOC	Other  Man-Months					
Materials Originator Gary Gavigan	Signature /	HAM .		28-71	P4,-	48 ate
Office I&O/M&O Office Manager	Signature		ک ک	8 Cg	5 % Di	ate
Disposition Approved	Approved w/Com	nment Fo	orward	Disa	prove	d 🗀
Comments:					1	
CCB Chairperson	Jan St.	mut		4/	29/9	78 

ORIGINAL

CM CLO

ECS